



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 20, 2013

Reviewed: 

Mine Name: Bear Lake Aggregate	Permit Number: S/033/0005
Operator Name: Yale Johnson	Inspection Date: May 2, 2013
Inspector(s): Lynn Kunzler	Time: 12:30 pm
Other Participants: None	Mine Status: active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection.

Inspection Summary:

Permit fees have not been paid for this year. The operator owes \$150.00. The site is bonded, however the operator still needs to sign and return the reclamation contract.

There has been little activity since my last inspection. It did not appear as if any material had been removed, just a little clean-up work. There was no mining equipment on site.

Photos were taken to document site conditions

Conclusions and Recommendations:

The operator needs to complete the reclamation contract and remit the annual permit fee of \$150 before he begins operations for this year.

Inspector's Signature

cc: Yale Johnson, Operator

John Blake, SITLA (jblake@utah.gov)

O:\M033-Rich\S0330005-BearLakeAggregate\inspections\ Insp-05022013.doch